



The simplest DC machine

2. Getting DC voltage out of a rotating loop


A voltage out of the loop is alternatively a constant positive value and a constant negative value.

One possible way to convert an alternating voltage to a constant voltage is by adding a commutator

segment/brush circuitry to the end of the loop. Every time the voltage of the loop switches direction, contacts switch connection.





The simplest DC machine



segments

brushes





Copyright Dr Andy Knight, 2013

The simplest DC machine

The tangential velocity of the loop's edges is


$$v = r\omega \quad (5.8.1)$$

where r is the radius from the axis of rotation to the edge of the loop. The total induced voltage:

$$e_{tot} = \begin{cases} 2r\omega Bl & \text{under the pole faces} \\ 0 & \text{beyond the pole edges} \end{cases} \quad (5.8.2)$$

The rotor is a cylinder with surface area $2\pi rl$. Since there are two poles, the area of the rotor under each pole is $A_p = \pi rl$. Therefore:

$$e_{tot} = \begin{cases} \frac{2}{\pi} A_p B \omega & \text{under the pole faces} \\ 0 & \text{beyond the pole edges} \end{cases} \quad (5.8.3)$$



The simplest DC machine

Assuming that the flux density B is constant everywhere in the air gap under the pole faces, the total flux under each pole is

$$\phi = A_p B \quad (5.9.1)$$

The total voltage is

$$e_{tot} = \begin{cases} \frac{2}{\pi} \phi \omega & \text{under the pole faces} \\ 0 & \text{beyond the pole edges} \end{cases} \quad (5.9.2)$$

The voltage generated in any real machine depends on the following factors:

1. The flux inside the machine;
2. The rotation speed of the machine;
3. A constant representing the construction of the machine.

The simplest DC machine

3. The induced torque in the rotating loop



Assuming that a battery is connected to the DC machine, the force on a segment of a loop is:

$$F = i(\mathbf{l} \times \mathbf{B}) \quad (5.12.1)$$

And the torque on the segment is

$$\tau = rF \sin \theta \quad (5.12.2)$$

Where θ is the angle between r and F . Therefore, the torque is zero when the loop is beyond the pole edges.



The simplest DC machine

When the loop is under the pole faces:

1. Segment ab :
$$F_{ab} = i(\mathbf{1} \times \mathbf{B}) = ilB \quad (5.13.1)$$

$$\tau_{ab} = rF \sin \theta = r(ilB) \sin 90^\circ = rilB \quad ccw \quad (5.13.2)$$

2. Segment bc :
$$F_{ab} = i(\mathbf{1} \times \mathbf{B}) = 0 \quad (5.13.3)$$

$$\tau_{ab} = rF \sin \theta = 0 \quad (5.13.4)$$

3. Segment cd :
$$F_{ab} = i(\mathbf{1} \times \mathbf{B}) = ilB \quad (5.13.5)$$

$$\tau_{ab} = rF \sin \theta = r(ilB) \sin 90^\circ = rilB \quad ccw \quad (5.13.6)$$

4. Segment da :
$$F_{ab} = i(\mathbf{1} \times \mathbf{B}) = 0 \quad (5.13.7)$$

$$\tau_{ab} = rF \sin \theta = 0 \quad (5.13.8)$$

The simplest DC machine

The resulting total induced torque is

$$\tau_{ind} = \tau_{ab} + \tau_{bc} + \tau_{cd} + \tau_{da} \quad (5.14.1)$$

$$\tau_{ind} = \begin{cases} 2rilB & \text{under the pole faces} \\ 0 & \text{beyond the pole edges} \end{cases} \quad (5.14.2)$$

Since $A_p \cong \pi r l$ and $\phi = A_p B$ (5.14.3)

$$\tau_{ind} = \begin{cases} \frac{2}{\pi} \phi i & \text{under the pole faces} \\ 0 & \text{beyond the pole edges} \end{cases} \quad (5.14.4)$$

The torque in any real machine depends on the following factors:

1. The flux inside the machine;
2. The current in the machine;
3. A constant representing the construction of the machine.